HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

Concord Gas Company: Gasholder House South Main Street Concord Merrimack County New Hampshire HAER No. NH-7

NOTE: These photographs are government materials and not subject to copyright. However, the courtesy of a credit line identifying the Historic American Engineering Record and the photographer would be appreciated. All photographs were taken by Gary Samson in August 1982.

GASHOLDER HOUSE

NH-7-1	General view of site looking NW.
NH-7-2	General view of site looking W.
NH-7-3	Closer in view of site looking NW.
NH-7-4	Telephoto view of site looking NW.
NH-7-5	View of Gasholder House looking E.
NH-7-6	View of Gasholder House looking NW.
NH-7-7	Closer in view of Gasholder House looking NW.
NH-7-8	View of Gasholder House looking N.
NH-7-9	Detail view of Gasholder House, looking N, showing valve house entry and members of team recording structure.
NH-7-10	Detail view of Gasholder House roof and cupola.
NH-7-11	Interior view of roof looking up to cupola.
NH-7-12	Interior view of Gasholder House showing wall, window, gasholder guide sheaves and stair to cupola.
NH-7-13	Interior view looking from inside Gasholder House through doorway to valve house.
NH-7-14	Detail view of gasholder guide sheave, and rail attached to interior wall.

Concord Gasholder House HAER No. NH-7 Index to Photographs Page 2

GASHOLDER HOUSE (Continued)

NH-7-15 Interior view showing top of gasholder tank and inlet cylinder.

NH-7-16 Detail view of inlet cylinder.